

Quality & Productivity Solutions

SPC

OEE

MONITORING

TRACEABILITY

WIP TRACKING






SPC Charts Email Alarms Data Collection Gauge Interfacing Production Reports

Monitoring

FACSMonitor[™] gives you the opportunity to view processes, current production rates and machine efficiencies in **real time**. All data collected is maintained in MS SQL, Oracle or similar databases for long term storage and historical analysis.







FACSMonitor[™] Features

- Machine up / down, run / idle times graphically and numerically
- Real-time events / alarms notification via:
 - E-mail alarm notifications
 - Digital paging / TXT messaging
 - Windows messaging
- Drill down to specific:
 - Country, state, plant, department, cell, workstation, machine, process and feature
- · Automatically drill down for selected events
- · Change displays to zoom in on priority events / alarms
- Production parts counts to plan
 - Know where you stand before you get behind
 - Be aware that you will need to run overtime well in advance
- Graphs by hour, shift, day, week or month
- All displays are user configured
 - Use any standard JPG, GIF, TIFF or BMP files
 - Take pictures of your actual cells and machines
- Multiple plants, departments and cells
 - Alternate displays between plants in different states
- Scan each department periodically
 - Temporarily zoom in on a problem department
- Banner messages
 - Congratulate the team with the best safety record
 - Welcome the newest associate to the company
 - Announce a birthday, anniversary or meeting

OEE

You can keep an eye on the Overall Equipment Effectiveness (OEE) of your plant or department as well as the details regarding availability, performance and quality of each machine. OEE Data is collected on the floor using the FSWorks Software. Machines can be connected using OPC, TCP/IP, RS-232 or by using discreet switches.

OEE Collection



When a machine goes down or becomes idle, the operator can be prompted to select the cause of the work stoppage.

| Factory Audit and Control System OEE Chart - Windows Internet Explorer | 🗉 🖻 🔀 | Factory Aud | it and Control Sy | stem Qui | k Report - Windows In | ternet Ex | ploter | | | | EF |
|---|---|-------------------------|---------------------------------------|-------------------|--------------------------|----------------|------------|---|------------------------------|-----------------------|-------|
| 💽 • 🕑 http://acabled.tecs.Form/Charter/SeeChart.seps | 🖌 🕂 🗶 Los Saers 🖉 . | 00- almp | /Jacalhost/Tacs/Form/Re | porter/QuickRepor | t.aspic1gruid=4 | | | | (v +₂) × | Live Search | |
| File Edit View Fevorites Tools Halp | | File Edit View | Favoritos Tools Help | | | | | | | | |
| 🔗 💋 Fectery Aulit and Central System 1 OEE Chart 🧰 | 🚯 • 🗇 – 📾 • 🕞 Page • 🕲 Tools • * | · · | Audit and Control Sesters | 1 Charle Ba | | | | | 1.45 - | El - 40 - () Tage - 0 | Tecia |
| | | but block and | | 1000000000 | - | | | 1. (A.S.) | and the second second | and the subscription | |
| THE ADDIMICS TO, PITTE | - See | PACS Rep | ets Charts | Spec Editor | Communications | CEE Op | line. | Ulilies Activist | raften | | |
| FAC8 Reports Cheets Spec Editar Conventications CEE Options Utilities | Administration | WEACS | | | | | | | | | |
| | | H Reports | | | OE | E Runtime - | OEE | CONTRACTOR OF THE OWNER | | 2 | |
| FAC5 Department MRU 💌 Machine (6870101 | | Cenerate | | | Date Range: 6/20/2 | 007 6-30 AN | 1-8/20/2 | 007 2:29 PM | | | |
| # Repots | | Report Build Report | | | | | | | | | |
| Charts Start 3/15/2007 Hour 0 Vinute 0 End 5/16/2007 Univer 0 Marute 0 | | Tamplate | | | | | | | | | |
| Costs Included Shits | | - Build Quick Report | | | armente Quelles SEE Sees | Parts God fait | a Luisi fe | | na Avacasa Cusis | | |
| - Build Chart @ At C First Submit | | · CLark Paper | 1 6870121 WS8285 2 68707231 WS8285 | | | 0 | | EE-59 50 000 00-00 00.000 | | | |
| | | IN COMPANY | | | | | 2 | 48-59-49.000 00:00 00.000 | 39-62-02.774 | | |
| a Quer Oran Availability : 33-48 % Freemandates Qtv.Occ | N Label // | # Spec Editor | 3 68/0003 W58287 4 6870103 W58287 | | 0 % 100.00 % 48.03 % 266 | 10 | 600 | 02159/59.000 00:00.52.000 02159/59.000 00:00.52.000 | 20-01-19-203 00-01-24-451 | | |
| a Spec Editor Performance : s1 45 % [1976 | 46.48 % Blocked Conveyor full | # Communication | | | | | | CE-59-59 CCC 00-03-00-000 | 37-01-06.321 | | |
| Communications Quality 1 0.66 % 251 | 11.96.% | W DEE Options | 5 6870401 W56261 6 6870602 W68264 | | | | 225 | CE-59-59-000 00-01-08-000 | 00-01-18.978 | | |
| | 0 22 % First Piece / Periodic | i Unining | 7 AN70107 WSK293 | | | | 141 | 18-59-19 000 00-01-12 050 | | | |
| | ver A checks | a Administration | | | | 0 | LAI | | 35-01-20,953 | | |
| Advisation Gene 1 | 7.66 % Cleaning | - 14 YO MONTON | 8 6670733 WSE282 | | | | 1.0 | 18:39:49.000 00:00.000 | 00/02/02.779 | | |
| Time : 75.03:11:21 | 5 13 % Staned-No parts | | 9 6870421 W38281 10 6870421 W38281 | | | | | 68-59-59-000 00:00 00.000 08-59-59-000 00:00 00.000 | 20 01:06.321 20 01:06.321 | | |
| Scheduled 1 73.15(45)56 127 | SS1% Desais | | 10 GE70421 WEEDED | | | | | 08-59-49.000 00-00 00.000 | 30-51-02.779 | | |
| | 5.54 % Equipment Fault | | LI MERCINI WEEKE | | | | 1 | E8-59-54 CCC 00-00 00.000 | 00-00-19-363 | | |
| Red Parts: 0 50 | 2.41% Operator Fast | | 13 0070733 W54292 | | | | - | CE:3W 49 CCC 00:00 00.000 | | 45:56:43.000 | |
| Ideal 00:00:56.8250000 | and the second se | | 14 0070102 W34203 | | | 10 | | 28.59.39.000 00.00.00.000 | 00.01.20.955 | | |
| A CONTRACT OF A | | | 15 6870700 W56060 | | | - | 133 | 06.53.49.000 00.02.07.000 | | | |
| | no Supervised Abel anno 1 | | 16 6870632 W58354 | | | 0 | | 05-59-19.000 00-00.000 | 00-01-18.978 | | |
| | 79.31 % Blocked-Conveyor full 7.14 % Operator Fault | | 17 ME70E12 WSELES | | | 1 | - | 18-59-59 (CE 00-53 00.000 | 30-61-20 953 | | |
| | 2.84 % Planed Setap Time | | 18 MERCENE WESTERS | | | 12 | | | 32-C1:18.203 | | |
| 175 111 | 2.84 % Planted Set op Time 2.73 % Break | | 18 9870003 W58287 | | | 0 | - | 58:59:59.000 00:00.000 | | | |
| | | | | | | 0 | | 15-59-19.000 00.00 00.000 | 00.01:19.203 | | |
| 100 100 | 152 % Cleaning | | 20 0070401 WS0001 | | | 10 | 275 | 68:59.59.000 (0:00 36.300 88:58:59.000 (0:00 36.300 | | | |
| | | | 21 6870622 W08264 | | | 10 | | | 30-01/18.979 | | |
| 18.38 | 161% checks | | 22 6820233 WS8393 | | | 10 | | 00100-00100-00100-000 | 89-51-02.778 | | |
| - 1107 | 1 18 % Staned-No parts | | 23 6870131 W54385 | | | 0 | 92 | 000.00.00100 000.00.000 | | 08:14:24,000 | |
| 1 UV | | | 24 0070733 W58382 | | | 0 | 12 | 0E.59.49.000 00.32.07.000 | 33-62-02.779 | | |

Graphical charts and detailed reports will assist in identifying bottlenecks in productivity. Both charts and reports can be exported to Excel[™] to share with other quality applications and/or for further analysis.

SPC

FACS[™] (Factory Audit and Control System) is browser-based software and offers central management of factory floor SPC and quality control information. Quality plans, charts, reports and system administration for all your CimStat[®] Factory Workstations are managed by FACS[™]. **This package runs under the latest versions of Windows and contains the following:**

FACS[™] Spec Editor

| | Control Lyssem (List Parts | Annual 1971 | and the later la | 0.0 | m 15 fage + (3 face - |
|---|---|--|--|-----|-----------------------|
| TACA. | Department (News For State (See 2) See | | 110 | | |
| EM Spect Can Advance Spece Can Advance Specee Advance Speceee Advance Speceee | Backback Backbackback Backbackback Backbackbackbackbackbackbackbackbackbackb | Appendix (Proceedings) B Record Construction 000< | Fastyn B New N Votellity Asternet | | |


With **Spec Editor**, the administrator is able to create and maintain variable and attribute quality plans for distribution to the CimStat[®] Factory Workstations on the factory floor. The quality plans are placed into "Setup" files along with configuration parameters, process events (assignable causes), automatic trend alarms, etc. These files are made available to the operator on the factory floor.

FACS[™] Chart

| · · · | restorchet.egs | | (19) (m) (m) (m) | 1e |
|---|-----------------------|---------------------------------------|---|-------------------|
| Fis All Ver Faulte Talk 149 | | | | |
| 🖉 📽 🗐 Feiture, Hudd and Cantod Jossen | 10LOwt | | 0-B #-D | Fage * (3 Tasis * |
| and the second se | | | | |
| AVES - Balante - (Darks | Res Table Generations | NE Same Labor | Alteration (| _ |
| OFF Comment OFF Comme | | 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | And | |

Chart produces popular statistical charts such as Xbar, R, Pareto, Sigma and Histogram for both variable and attribute analysis. With Charts, the user may further analyze a process by monitoring the natural limits of the process, the impact of improvements to the process and, like Report, identify potential problems before they evolve into critical situations.

FACS[™] Report



Report is used to generate comprehensive reports, which compliment the SPC charting functions. Summary reports can be created for any process being monitored by FSWorks[™] on the factory floor. And, using the SORT feature, the user can identify the process with the poorest CPK (for example). Report also includes the ability to specify flags for indicating the presence of events (out-of-tolerance conditions), which may require further SPC analysis.

TRACEABILITY & TRACKING

FACS[™] reports can also trace a single part identified by a unique serial number through each operation of the production process. Scanning a serial number in FSWorks allows for real time tracking of part location in a predefined workflow.


TRACEABILITY

| | O http://localhost | | | | | | _ | - | | _ | | • + × |
|---|-----------------------|-------------------------------------|--|--|---|---|--|---|---|---|--|------------|
| X Statch the | ie Web | P. 5 | earch + AC |)L 🄄 🖬 | to 6New T | 2 Wea | ther * | Gas Prices | * 📚 Find Related Content | | | |
| Favorites | 🍰 🔭 Courtyard | is at 411 | Meetin 🔏 | Suggested S | Sites 🔻 👩 G | et More A | dd-ons * | | | | | |
| C Factory Au | udit and Control Syst | em I Rei | porter | | | | | | | | | (i) • (ii) |
| Q | | 1.0 | | | | | | | | | Administrator Logout | |
| SIFAC | S ⁰ | | | | | | 655 | | | Activ | e Sessions: 1 Max: 99 | |
| ACTORY AUDIT A | ND CONTROL SYSTEM | | | | | | E. | | | My Accourt | nt Global Preferences | |
| FACS | Reports | C | harts | Spec Ed | itor | Comr | municatio | ons | OEE Options | Utilities | Administration | |
| | | | | | | | | | | | | |
| E FACS | | | | | | (Trace | ability) | Serial Nu | mber | | | |
| E Reports | | _ | | D | ate Range | | | | 31/2010 12:00 AM | | | |
| | | | | | | | | | | | | |
| Charts- | | | | Eve | nt: Serial | Numbe | r - Con | nment: 17 | 5L8753203701H070 | | | |
| Charts | Liter | | | Eve | nt: Serial | Numbe | r - Con | nment: 17 | 5L8753203701H070 | | | |
| Spec E | | | | Eve | nt: Serial | Numbe | r - Con | nment: 17 | 5L8753203701H070 | | | |
| Spec E Communication | unications | | | Eve | nt: Serial | Numbe | r - Con | nment: 17 | 5L8753203701H070 | | | |
| Spec E Commu OEE O | unications lptions | | Department | | | | | | | Serial Number | | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 | Department | Part | Operation | Machine | Feature | Reading | DeteTime | Serial Number | 270 | |
| Spec E Commu OEE O | unications Iptions | 1 | Department Demo Demo | Part 7200 Drive | | Machine Tester | | Reading 12600.0000 | DateTime 03/19/2010 09:46:00 AM | 175L8753203701H0 | | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 2 3 | Demo | Part 7200 Drive 7200 Drive | Operation Speed Test | Machine Tester Tester | Feature RPM 1 | Reading 12600.0000 | DateTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 | 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 2 3 4 | Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test | Machine Tester Tester Tester | Poature RPM 1 RPM 2 | Reading 12600.0000 12600.0000 | DateTime 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 070 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 2 3 4 5 | Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester | Peature RPM 1 RPM 2 RPM 3 | Reading 12600.0000 12600.0000 6321.0000 | DateTime 03/19/2010 09:45:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 070 070 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 2 3 4 5 6 | Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester | Peature RPM 1 RPM 2 RPM 3 RPM 4 | Reading 12600.0000 12600.0000 6321.0000 0.0000 | DateTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 070 070 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | 1 2 3 4 5 6 7 | Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester | Peature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 | Reading 12600.0000 12600.0000 6321.0000 0.0000 -1.0000 | DataTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 070 070 070 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | - | Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester | Feature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 6 | Reading 12600.0000 12600.0000 6321.0000 0.0000 -1.0000 0.0132 | DateTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 070 070 070 070 070 | |
| Spec E Commu OEE O Utilities | unications Iptions | - | Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester | Feature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 6 RPM 7 | Reading 12600.0000 12600.0000 6321.0000 0.0000 -1.0000 0.0132 402.7880 | DateTime 03/19/2010 09-45-00 AM 03/19/2010 09-46-00 AM 03/19/2010 09-46-00 AM 03/19/2010 09-46-00 AM 03/19/2010 09-46-00 AM 03/19/2010 09-46-00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 970 970 970 970 970 970 | |
| Spec E Commu OEE O Utilities | unications Iptions | 7 8 9 | Demo Demo Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester Tester | Feature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 6 RPM 6 RPM 7 RPM 0 RPM 9 | Reading 12600.0000 6321.0000 0.0000 0.0000 0.0132 402.7880 296.8191 | DatoTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 270 274 270 270 270 270 270 270 | |
| Spec E Commu OEE O Utilities | unications Iptions | 7 8 9 10 | Demo Demo Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester Tester Tester | Feature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 6 RPM 6 RPM 7 RPM 0 RPM 9 | Reading 12600.0000 6321.0000 0.0000 0.0132 402.7880 296.8191 799.6456 | DateTime 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM 03/19/2010 09:46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 270 274 275 270 270 270 270 270 270 | |
| Spec E Commu OEE O Utilities | unications Iptions | 7 8 9 10 11 | Demo Demo Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive 7200 Drive | Operation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester Tester Tester | Feature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 6 RPM 6 RPM 7 RPM 0 RPM 9 RPM 10 | Reading 12600.0000 12600.0000 6321.0000 0.0000 -1.0000 0.0132 402.7880 396.8181 799.6456 210.8591 | Data Time 03/19/2010 09-46:00 AM 03/19/2010 09-46:00 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 270 270 270 270 270 270 270 270 270 270 | |
| Spec E Commu OEE O Utilities | unications Iptions | 7 8 9 10 11 12 | Demo Demo Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive | Cperation Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester Tester Tester Tester Tester | Peature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 5 RPM 5 RPM 5 RPM 5 RPM 9 RPM 10 RPM 1 | Reading 12600.0000 12600.0000 0.0000 -1.0000 0.0132 402.7880 296.8181 796.6456 210.8591 4822.0000 | DataTime 03/19/2010 09-45100 AM 03/19/2010 09-45100 AM | 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 175L8753203701H0 | 270 270 270 270 270 270 270 270 270 270 | |
| Spec E Commu OEE O Utilities | unications Iptions | 7 U 9 10 11 12 13 | Demo Demo Demo Demo Demo Demo Demo Demo | Part 7200 Drive 7200 Drive | Operation Speed Test Speed Test | Machine Tester Tester Tester Tester Tester Tester Tester Tester Tester Tester Tester Tester | Peature RPM 1 RPM 2 RPM 3 RPM 4 RPM 5 RPM 5 RPM 5 RPM 5 RPM 5 RPM 9 RPM 9 RPM 10 RPM 1 RPM 2 | Reading 12600.0000 6321.0000 0.0000 -1.0000 0.0132 402.7880 396.8181 799.6456 210.8591 4022.0000 | Data Time 03/19/2010 09-46100 AM 03/19/2010 09-47100 AM 03/19/2010 09-47100 AM | 1754753203701H0 1754753203701H0 1754753203701H0 1754753203701H0 1754753203701H0 1754753203701H0 1754753203701H0 17548753203701H0 17548753203701H0 17548753203701H0 17548753203701H0 | 270 270 270 270 270 270 270 270 270 270 | |

Parts can be traced by lot, batch, serial number or even by operator. Trace reports can show at what time and date a particular part or batch was processed at each operation.

If a customer has a question about a particular serial number, a trace report can show the actual dimensions for that part at time of manufacture.

TRACKING



Once the operational workflow is been defined, FACSTrack can track a part through the production process and alternately alert the operator if a part has skipped or failed a previous operation.



SPC


FSWorks[™] runs on the latest version of Windows. The FSWorks[™] data entry screen can be easily configured by the user to show real time bar graphs for virtually any number of variable features as well as the actual readings in




numeric format and a continually updating graph. The bar graphs change colors depending on whether the readings are within spec, out of spec or out of control. You can take a picture of your parts and include them on the data entry screens. Screens may also allow for entry of attribute data such as Go / No Go and specific defects.









FSWorks[™] Features

- Change parts at the touch of a button
- Data entry methods:
 - Manual data entry via keyboard or touch screen keypad
 - Probes, fixtures and gauges
 - Serial Ports
 - Virtual Ports (files)
 - ODBC
 - OPC
- Monitor machine or work center efficiency:
 - Record machine up / down / run / idle
 - Part counters
- Switches
- Timers
- Discrete outputs
- User programs executed based on events
- GR&R
- Erroneous data detection
- User configured alarms
- Charts and Reports:
 - Xbar
 - Individuals
 - Histograms
 - Moving Average
 - Cumulative Sum
 - Collection History
 - Box and Whiskers
 - Process Overview
 - Production History
 - C-Chart
 - P-Chart
 - NP-Chart
 - U-Chart
 - Pareto
- Triggers for external enunciators
- User definable trend levels
- Operator notification

Quality & Productivity Solutions

www.factorysystems.net



Quotation Services

We can quote from blueprints and sample parts as well as on-site visits to determine the system to meet the customer's needs, both technical and budgetary.

Custom Programming

Factory Systems can program their equipment to interface with virtually any electronic device. Custom programming can also simplify the use of the system.

Custom Hardware

Factory Systems provides fixtures and control panels to further simplify operation. Common tasks are reduced to single push buttons.

Installation

Factory Systems staff can come to your site and fully install the equipment, complete with programming for your specifications.

Training

On-site training is available with the initial installation. More advanced training, as well as courses for new users are available, both on-site, and at our facility in South Carolina.

Technical Support

Our staff is available to support the customer's needs via a toll-free number. Complete remote access support via VPN or other secure networks.



Factory Systems, LLC Columbia, South Carolina www.factorysystems.net sales@factorysystems.net toll free 800-868-7481